


**THE FOLLOWING CARDS ARE
DISTRIBUTED AROUND THE
TRAINING ROOM IN
DIFFERENT LOCATIONS.
PARTICIPANTS CAN ASK
FURTHER INFORMATION OF
COMMUNITY MEMBERS. THEY
SHOULD THEN RECOMMEND
ANY APPROPRIATE TESTING,
PROTECTION, TREATMENT
AND SIGNS TO BE POSTED**

PRINT DOUBLE SIDED



Dismantled well

Reason: insufficient drill depth, hardware used elsewhere.





Tippy Tap

Location: village community house (used for mobile clinic visits) Status: empty.



Unprotected well

Location: village periphery. Status: functional.



Dismantled well 2

Reason: insufficient drill depth, hardware used elsewhere.





Tube well

Location: Near school but public. Status:
functional. Good flow. Estimated 60m.
Superficial cracks to apron.



Tube well 2

Location: Near mosque but public. Status: functional. Some evidence of loss of flow (requires delay between pumping) but adequate. Estimated 40m



Internet Café

Location: Centre of town. The café also serves water (free) and other drinks (sold).



Surface water

Location: River on edge of village.



Commercial cooking

Location: Centre of town adjacent to internet café. Stall selling boiled and fried food.

Cooked to order. Chicken, fish, potatoes. Free water with food, Coke, Fanta.

**THE FOLLOWING
CARDS ARE ONLY
REVEALED IF THEY ASK
FOR INFORMATION
ABOUT THE CAFÉS**

PRINT DOUBLE-SIDED



Water trucking for commercial properties

Source: tube well with diesel pump in nearest
large town. Protected



Storage container

Location: Behind internet café. Used solely by café. Status: Private, raised on brick platform.

Tap for extraction. Capacity 7200 litre